

## INSPECTION RESULTS BELOW



- This is a Free Third Party Inspection for the Consumer
- This is an independent finding with no bias from EVO Motors

Please Sign, Print & Date to Acknowledge Results

Sign \_\_\_\_\_ Print \_\_\_\_\_ Date \_\_\_\_\_



## INSPECTION ANALYSIS:



# PASS

| Vehicle Information    |       |
|------------------------|-------|
| Year                   | 2018  |
| Make                   | KIA   |
| Model                  | FORTE |
| VIN: 3KPFK4A72JE197253 |       |

T.I.C.S.  
COSMETIC  
SCORE

# 96

T.I.C.S.  
STRUCTURAL  
SCORE

# 100

T.I.C.S.  
ANALYSIS  
CERTIFIED




**VERY MINOR COSMETIC  
REPAIRS FOUND**

| Inspection Information |                  |
|------------------------|------------------|
| Mileage                | 33658            |
| Date                   | 02/04/21         |
| Location               | Seffner, Florida |
| Inspector              | Scott Foley      |
| Order Number           | 45967            |



| Cosmetic              | Analytics |
|-----------------------|-----------|
| Front Bumper Cover    | Original  |
| Rear Bumper Cover     | Repaired  |
| Hood                  | Original  |
| Cladding              | N/A       |
| Trunk/Hatch/Tailgate  | Original  |
| Right Fender          | Original  |
| Right Front Door      | Original  |
| Right Rear Door       | Original  |
| Right Cosmetic Rocker | Original  |
| Right Cab Corner      | N/A       |
| Right Quarter Panel   | Original  |
| Right Bedside         | N/A       |
| Right Roof Rail       | Original  |
| Roof                  | Original  |
| Left Fender           | Original  |
| Left Front Door       | Original  |
| Left Rear Door        | Original  |
| Left Cosmetic Rocker  | Original  |
| Left Cab Corner       | N/A       |
| Left Quarter Panel    | Repaired  |
| Left Bedside          | N/A       |
| Left Roof Rail        | Original  |

\*If any, Repairs will be noted on vehicle with RED indicator.



## Special Notes:



OBD2 Diagnostic -

CLEAR



No Check Engine Lights

| Structural            | Body |      |
|-----------------------|------|------|
| Left Quarter Panel    |      | Pass |
| Right Quarter Panel   |      | Pass |
| Roof                  |      | Pass |
| Left A Pillar         |      | Pass |
| Left B Pillar         |      | Pass |
| Left C Pillar         |      | Pass |
| Left D Pillar         |      | Pass |
| Right A Pillar        |      | Pass |
| Right B Pillar        |      | Pass |
| Right C Pillar        |      | Pass |
| Right D Pillar        |      | Pass |
| Left Rocker           |      | Pass |
| Right Rocker          |      | Pass |
| Left Rear Strut Tower |      | Pass |
| Rear Body Panel       |      | Pass |

| Underhood        | Structural |      |
|------------------|------------|------|
| Cross Member     |            | Pass |
| Core Support     |            | Pass |
| Firewall         |            | Pass |
| Left Apron       |            | Pass |
| Right Apron      |            | Pass |
| Left Frame Rail  |            | Pass |
| Right Frame Rail |            | Pass |

Each Transparency Inspection is performed by a trained technician using the latest in technology and industry experience. This report is limited to the vehicle's condition on the date the inspection was completed. This is not a warranty, or guarantee, when/in unreachable components or work done after inspection.



## CERTIFICATE OF ANALYSIS

Integrity of Inspection, Excellence, experience

**2018 KIA FORTE**  
**VIN: 3KPFK4A72JE197253**

---

Each Transparency Inspection is performed by a trained technician using the latest in technology experience.

**02/04/2021**

CHIEF INSPECTION OFFICER