



INSPECTION RESULTS BELOW



- This is a Free Third Party Inspection for the Consumer
- This is an independent finding with no bias from EVO Motors

Please Sign, Print & Date to Acknowledge Results

Sign _____ Print _____ Date _____



INSPECTION ANALYSIS:



PASS

Vehicle Information	
Year	2020
Make	NISSAN
Model	ALTIMA
VIN: 1N4BL4BV8LC247453	

T.I.C.S.
COSMETIC
SCORE

90

T.I.C.S.
STRUCTURAL
SCORE

100

T.I.C.S.
ANALYSIS
CERTIFIED




Inspection Information	
Mileage	7422
Date	4/26/21
Location	Seffner, Florida
Inspector	Scott Foley
Order Number	45967

COSMETIC REPAIRS FOUND



Cosmetic	Analytics
Front Bumper Cover	Repaired
Rear Bumper Cover	Repaired
Hood	Original
Cladding	N/A
Trunk/Hatch/Tailgate	Original
Right Fender	Original
Right Front Door	Original
Right Rear Door	Original
Right Cosmetic Rocker	Original
Right Cab Corner	N/A
Right Quarter Panel	Original
Right Bedside	N/A
Right Roof Rail	Original
Roof	Original
Left Fender	Original
Left Front Door	Repaired
Left Rear Door	Repaired
Left Cosmetic Rocker	Original
Left Cab Corner	N/A
Left Quarter Panel	Repaired
Left Bedside	N/A
Left Roof Rail	Original

*If any, Repairs will be noted on vehicle with RED indicator.



Special Notes:



OBD2 Diagnostic -

CLEAR



No Check Engine Lights

Structural	Body
Left Quarter Panel	Pass
Right Quarter Panel	Pass
Roof	Pass
Left A Pillar	Pass
Left B Pillar	Pass
Left C Pillar	Pass
Left D Pillar	Pass
Right A Pillar	Pass
Right B Pillar	Pass
Right C Pillar	Pass
Right D Pillar	Pass
Left Rocker	Pass
Right Rocker	Pass
Left Rear Strut Tower	Pass
Rear Body Panel	Pass

Underhood	Structural
Cross Member	Pass
Core Support	Pass
Firewall	Pass
Left Apron	Pass
Right Apron	Pass
Left Frame Rail	Pass
Right Frame Rail	Pass

Each Transparency Inspection is performed by a trained technician using the latest in technology and industry experience. This report is limited to the vehicle's condition on the date the inspection was completed. This is not a warranty, or guarantee, when/in unreachable components or work done after inspection.



CERTIFICATE OF ANALYSIS

Integrity of Inspection, Excellence, experience

2020 NISSAN ALTIMA
VIN: 1N4BL4BV8LC247453

Each Transparency Inspection is performed by a trained technician using the latest in technology experience.

04/26/2021

CHIEF INSPECTION OFFICER