

INSPECTION RESULTS BELOW



- This is a Free Third Party Inspection for the Consumer
- This is an independent finding with no bias from EVO Motors

Please Sign, Print & Date to Acknowledge Results

Sign _____ Print _____ Date _____



INSPECTION ANALYSIS:



PASS

Vehicle Information	
Year	2018
Make	TOYOTA
Model	COROLLA
VIN: 2T1BURHE4JC048691	

T.I.C.S.
COSMETIC
SCORE

96

T.I.C.S.
STRUCTURAL
SCORE

100

T.I.C.S.
ANALYSIS
CERTIFIED




Inspection Information	
Mileage	17284
Date	05/22/20
Location	Seffner, Florida
Inspector	Scott Foley
Order Number	45967

**VERY MINOR COSMETIC
REPAIRS FOUND**



Cosmetic	Analytics
Front Bumper Cover	Repaired
Rear Bumper Cover	Original
Hood	Repaired
Cladding	N/A
Trunk/Hatch/Tailgate	Original
Right Fender	Original
Right Front Door	Original
Right Rear Door	Original
Right Cosmetic Rocker	Original
Right Cab Corner	N/A
Right Quarter Panel	Original
Right Bedside	N/A
Right Roof Rail	Original
Roof	Original
Left Fender	Original
Left Front Door	Original
Left Rear Door	Original
Left Cosmetic Rocker	Original
Left Cab Corner	N/A
Left Quarter Panel	Original
Left Bedside	N/A
Left Roof Rail	Original

*If any, Repairs will be noted on vehicle with **RED** indicator.



Special Notes:



OBD2 Diagnostic -

CLEAR



No Check Engine Lights

Structural	Body	
		Left Quarter Panel Pass
		Right Quarter Panel Pass
		Roof Pass
		Left A Pillar Pass
		Left B Pillar Pass
		Left C Pillar Pass
		Left D Pillar Pass
		Right A Pillar Pass
		Right B Pillar Pass
		Right C Pillar Pass
		Right D Pillar Pass
		Left Rocker Pass
		Right Rocker Pass
		Left Rear Strut Tower Pass
		Rear Body Panel Pass

Underhood	Structural	
		Cross Member Pass
		Core Support Pass
		Firewall Pass
		Left Apron Pass
		Right Apron Pass
		Left Frame Rail Pass
		Right Frame Rail Pass

Each Transparency Inspection is performed by a trained technician using the latest in technology and industry experience. This report is limited to the vehicle's condition on the date the inspection was completed. This is not a warranty, or guarantee, when/in unreachable components or work done after inspection.



CERTIFICATE OF ANALYSIS

Integrity of Inspection, Excellence, experience

2018 TOYOTA COROLLA
VIN: 2T1BURHE4JC048691

Each Transparency Inspection is
performed by a trained technician using the latest
in technology experience.

11/22/2020

CHIEF INSPECTION OFFICER