

## INSPECTION RESULTS BELOW



- This is a Free Third Party Inspection for the Consumer
- This is an independent finding with no bias from EVO Motors

Please Sign, Print & Date to Acknowledge Results

Sign \_\_\_\_\_ Print \_\_\_\_\_ Date \_\_\_\_\_



## INSPECTION ANALYSIS:

 **PASS**

Vehicle Information	
Year	2018
Make	TOYOTA
Model	CAMRY
VIN: 4T1B11HK3JU538523	

T.I.C.S.  
COSMETIC  
SCORE

**96**

T.I.C.S.  
STRUCTURAL  
SCORE

**98**

T.I.C.S.  
ANALYSIS  
CERTIFIED




Inspection Information	
Mileage	7520
Date	05/22/20
Location	Seffner, Florida
Inspector	Scott Foley
Order Number	45967

### COMPLETED REPAIRS FOUND



Cosmetic	Analytics
Front Bumper Cover	Original
Rear Bumper Cover	Repaired
Hood	Original
Cladding	N/A
Trunk/Hatch/Tailgate	Original
Right Fender	Original
Right Front Door	Original
Right Rear Door	Original
Right Cosmetic Rocker	Original
Right Cab Corner	N/A
Right Quarter Panel	Repaired
Right Bedside	N/A
Right Roof Rail	Original
Roof	Original
Left Fender	Original
Left Front Door	Original
Left Rear Door	Original
Left Cosmetic Rocker	Original
Left Cab Corner	N/A
Left Quarter Panel	Original
Left Bedside	N/A
Left Roof Rail	Original

\*If any, Repairs will be noted on vehicle with **RED** indicator.



Structural	Body	
Left Quarter Panel		Pass
Right Quarter Panel		Pass
Roof		Pass
Left A Pillar		Pass
Left B Pillar		Pass
Left C Pillar		Pass
Left D Pillar		Pass
Right A Pillar		Pass
Right B Pillar		Pass
Right C Pillar		Pass
Right D Pillar		Pass
Left Rocker		Pass
Right Rocker		Pass
Left Rear Strut Tower		Pass
Rear Body Panel		Repaired

Underhood	Structural	
Cross Member		Pass
Core Support		Pass
Firewall		Pass
Left Apron		Pass
Right Apron		Pass
Left Frame Rail		Pass
Right Frame Rail		Pass

## Special Notes:



OBD2 Diagnostic -

CLEAR



No Check Engine Lights

Each Transparency Inspection is performed by a trained technician using the latest in technology and industry experience. This report is limited to the vehicle's condition on the date the inspection was completed. This is not a warranty, or guarantee, when/in unreachable components or work done after inspection.



## CERTIFICATE OF ANALYSIS

Integrity of Inspection, Excellence, experience

**2018 TOYOTA CAMRY**  
**VIN: 4T1B11HK3JU538523**

---

Each Transparency Inspection is  
performed by a trained technician using the latest  
in technology experience.

**11/22/2020**

CHIEF INSPECTION OFFICER