

INSPECTION RESULTS BELOW



- This is a Free Third Party Inspection for the Consumer
- This is an independent finding with no bias from EVO Motors

Please Sign, Print & Date to Acknowledge Results

Sign _____ Print _____ Date _____



INSPECTION ANALYSIS:



PASS

Vehicle Information	
Year	2021
Make	NISSAN
Model	ROGUE
VIN: 5N1AT3AA3MC694512	

Inspection Information	
Mileage	14437
Date	10/6/22
Location	Seffner, Florida
Inspector	Scott Foley
Order Number	45967




T.I.C.S. COSMETIC SCORE	T.I.C.S. STRUCTURAL SCORE	T.I.C.S. ANALYSIS CERTIFIED
88	98	

COMPLETED REPAIRS FOUND

	Cosmetic	Analytics
Front Bumper Cover		Refinished
Rear Bumper Cover		Refinished
Hood		Refinished
Cladding		N/A
Trunk/Hatch/Tailgate		Refinished
Right Fender		Original
Right Front Door		Original
Right Rear Door		Original
Right Cosmetic Rocker		Original
Right Cab Corner		N/A
Right Quarter Panel		Original
Right Bedside		N/A
Right Roof Rail		Original
Roof		Original
Left Fender		Original
Left Front Door		Original
Left Rear Door		Refinished
Left Cosmetic Rocker		Original
Left Cab Corner		N/A
Left Quarter Panel		Refinished
Left Bedside		N/A
Left Roof Rail		Original

*If any, Repairs will be noted on vehicle with RED indicator.



Structural	Body
Left Quarter Panel	Repaired
Right Quarter Panel	Original
Roof	Original
Left A Pillar	Original
Left B Pillar	Original
Left C Pillar	Original
Left D Pillar	Original
Right A Pillar	Original
Right B Pillar	Original
Right C Pillar	Original
Right D Pillar	Original
Left Rocker	Original
Right Rocker	Original
Left Rear Strut Tower	Original
Rear Body Panel	Original

Underhood	Structural
Cross Member	Original
Core Support	Original
Firewall	Original
Left Apron	Original
Right Apron	Original
Left Frame Rail	Original
Right Frame Rail	Original

Special Notes:



OBD2 Diagnostic - CLEAR



No Check Engine Lights

Each Transparency Inspection is performed by a trained technician using the latest in technology and industry experience. This report is limited to the vehicle's condition on the date the inspection was completed. This is not a warranty, or guarantee, when/in unreachable components or work done after inspection.