



## INSPECTION RESULTS BELOW



- This is a Free Third Party Inspection for the Consumer
- This is an independent finding with no bias from EVO Motors

Please Sign, Print & Date to Acknowledge Results

Sign \_\_\_\_\_ Print \_\_\_\_\_ Date \_\_\_\_\_



## INSPECTION ANALYSIS:



# PASS

Vehicle Information	
Year	2018
Make	TOYOTA
Model	COROLLA
VIN: 5YFBURHE9JP740252	

T.I.C.S.  
COSMETIC  
SCORE

## 92

T.I.C.S.  
STRUCTURAL  
SCORE

## 98

T.I.C.S.  
ANALYSIS  
CERTIFIED




Inspection Information	
Mileage	27413
Date	12/12/20
Location	Seffner, Florida
Inspector	Scott Foley
Order Number	45967

## COMPLETED REPAIRS FOUND



Cosmetic	Analytics
Front Bumper Cover	Original
Rear Bumper Cover	Repaired
Hood	Original
Cladding	N/A
Trunk/Hatch/Tailgate	Original
Right Fender	Original
Right Front Door	Original
Right Rear Door	Original
Right Cosmetic Rocker	Original
Right Cab Corner	N/A
Right Quarter Panel	Original
Right Bedside	N/A
Right Roof Rail	Original
Roof	Original
Left Fender	Original
Left Front Door	Original
Left Rear Door	Repaired
Left Cosmetic Rocker	Original
Left Cab Corner	N/A
Left Quarter Panel	Repaired
Left Bedside	N/A
Left Roof Rail	Original

\*If any, Repairs will be noted on vehicle with RED indicator.



## Special Notes:



OBD2 Diagnostic -

CLEAR



No Check Engine Lights

Structural	Body
Left Quarter Panel	Repaired
Right Quarter Panel	Pass
Roof	Pass
Left A Pillar	Pass
Left B Pillar	Pass
Left C Pillar	Pass
Left D Pillar	Pass
Right A Pillar	Pass
Right B Pillar	Pass
Right C Pillar	Pass
Right D Pillar	Pass
Left Rocker	Pass
Right Rocker	Pass
Left Rear Strut Tower	Pass
Rear Body Panel	Pass

Underhood	Structural
Cross Member	Pass
Core Support	Pass
Firewall	Pass
Left Apron	Pass
Right Apron	Pass
Left Frame Rail	Pass
Right Frame Rail	Pass

Each Transparency Inspection is performed by a trained technician using the latest in technology and industry experience. This report is limited to the vehicle's condition on the date the inspection was completed. This is not a warranty, or guarantee, when/in unreachable components or work done after inspection.



## CERTIFICATE OF ANALYSIS

Integrity of Inspection, Excellence, experience

**2018 TOYOTA COROLLA**  
**VIN: 5YFBURHE9JP740252**

---

Each Transparency Inspection is performed by a trained technician using the latest in technology experience.

**12/12/2020**

CHIEF INSPECTION OFFICER