



INSPECTION RESULTS BELOW



- This is a Free Third Party Inspection for the Consumer
- This is an independent finding with no bias from EVO Motors

Please Sign, Print & Date to Acknowledge Results

Sign _____ Print _____ Date _____



INSPECTION ANALYSIS:



PASS

Vehicle	Information
Year	2017
Make	NISSAN
Model	ROGUE
VIN: JN1BJ1CR7HW127927	

T.I.C.S.
COSMETIC
SCORE

94

T.I.C.S.
STRUCTURAL
SCORE

98

T.I.C.S.
ANALYSIS
CERTIFIED



Inspection	Information
Mileage	32763
Date	02/04/21
Location	Seffner, Florida
Inspector	Scott Foley
Order Number	45967

COMPLETED REPAIRS FOUND



	Cosmetic	Analytics
Front Bumper Cover		Original
Rear Bumper Cover		Repaired
Hood		Original
Cladding		N/A
Trunk/Hatch/Tailgate		Original
Right Fender		Original
Right Front Door		Original
Right Rear Door		Repaired
Right Cosmetic Rocker		Original
Right Cab Corner		N/A
Right Quarter Panel		Repaired
Right Bedside		N/A
Right Roof Rail		Original
Roof		Original
Left Fender		Original
Left Front Door		Original
Left Rear Door		Original
Left Cosmetic Rocker		Original
Left Cab Corner		N/A
Left Quarter Panel		Original
Left Bedside		N/A
Left Roof Rail		Original

*If any, Repairs will be noted on vehicle with **RED** indicator.



Special Notes:



OBD2 Diagnostic -

CLEAR



No Check Engine Lights

Structural	Body
Left Quarter Panel	Pass
Right Quarter Panel	Repaired
Roof	Pass
Left A Pillar	Pass
Left B Pillar	Pass
Left C Pillar	Pass
Left D Pillar	Pass
Right A Pillar	Pass
Right B Pillar	Pass
Right C Pillar	Pass
Right D Pillar	Pass
Left Rocker	Pass
Right Rocker	Pass
Left Rear Strut Tower	Pass
Rear Body Panel	Pass

Underhood	Structural
Cross Member	Pass
Core Support	Pass
Firewall	Pass
Left Apron	Pass
Right Apron	Pass
Left Frame Rail	Pass
Right Frame Rail	Pass

Each Transparency Inspection is performed by a trained technician using the latest in technology and industry experience. This report is limited to the vehicle's condition on the date the inspection was completed. This is not a warranty, or guarantee, when/in unreachable components or work done after inspection.



CERTIFICATE OF ANALYSIS

Integrity of Inspection, Excellence, experience

2017 NISSAN ROGUE
VIN: JN1BJ1CR7HW127927

Each Transparency Inspection is performed by a trained technician using the latest in technology experience.

02/04/2021

CHIEF INSPECTION OFFICER