

INSPECTION RESULTS BELOW



- This is a Free Third Party Inspection for the Consumer
- This is an independent finding with no bias from EVO Motors

Please Sign, Print & Date to Acknowledge Results

Sign _____ Print _____ Date _____



INSPECTION ANALYSIS:

 **PASS**

Vehicle Information	
Year	2018
Make	KIA
Model	SOUL
VIN: KNDJN2A28J7594850	

T.I.C.S.
COSMETIC
SCORE

90

T.I.C.S.
STRUCTURAL
SCORE

98

T.I.C.S.
ANALYSIS
CERTIFIED




Inspection Information	
Mileage	24771
Date	2/26/21
Location	Seffner, Florida
Inspector	Scott Foley
Order Number	45967

COMPLETED REPAIRS FOUND



Cosmetic	Analytics
Front Bumper Cover	Repaired
Rear Bumper Cover	Original
Hood	Repaired
Cladding	N/A
Trunk/Hatch/Tailgate	Original
Right Fender	Repaired
Right Front Door	Original
Right Rear Door	Original
Right Cosmetic Rocker	Original
Right Cab Corner	N/A
Right Quarter Panel	Original
Right Bedside	N/A
Right Roof Rail	Original
Roof	Original
Left Fender	Repaired
Left Front Door	Original
Left Rear Door	Original
Left Cosmetic Rocker	Original
Left Cab Corner	N/A
Left Quarter Panel	Original
Left Bedside	N/A
Left Roof Rail	Original

*If any, Repairs will be noted on vehicle with **RED** indicator.



Special Notes:



OBD2 Diagnostic -

CLEAR



No Check Engine Lights

Structural	Body	
Left Quarter Panel		Pass
Right Quarter Panel		Pass
Roof		Pass
Left A Pillar		Pass
Left B Pillar		Pass
Left C Pillar		Pass
Left D Pillar		Pass
Right A Pillar		Pass
Right B Pillar		Pass
Right C Pillar		Pass
Right D Pillar		Pass
Left Rocker		Pass
Right Rocker		Pass
Left Rear Strut Tower		Pass
Rear Body Panel		Pass

Underhood	Structural	
Cross Member		Pass
Core Support		Pass
Firewall		Pass
Left Apron		Pass
Right Apron		Pass
Left Frame Rail		Pass
Right Frame Rail		Passable Deflection

Each Transparency Inspection is performed by a trained technician using the latest in technology and industry experience. This report is limited to the vehicle's condition on the date the inspection was completed. This is not a warranty, or guarantee, when/in unreachable components or work done after inspection.



CERTIFICATE OF ANALYSIS

Integrity of Inspection, Excellence, experience

2018 KIA SOUL
VIN: KNDJN2A28J7594850

Each Transparency Inspection is performed by a trained technician using the latest in technology experience.

02/26/2021

CHIEF INSPECTION OFFICER